sday, Septen	nber 09, 2010 12:54:33 D4180-3	РМ	11000	2 HIII IIII II					Pag
, 1D:	D4180-3 PRELIM Gusset	mul	Acce	ept			 s	Setup Start	
	0/0/2010				Cust Item ID Customer:	1 :		Stop	
oprovals.	Process Plan: A	Date:		oling: C (Y/N):	Dat Dat		F	Run Start Stop	
equence ID/ York Center ID Draw Nbr	Operation Description Revision Nbr	1		Set Up/ Run Hours	Tool ID	Tool# Plan Code	Accept Qty		Reject Insp. Number Stamp
D4180			0.	.00					
Waterjet ELOW CNC Waterjet	I- D	Cut as per Dwg wg Rev: 01-1 og Rev: 01-1	0	.00			iß (c	9-13	
		Deburr if necessary							9
110	QC2- Inspect p	arts off machine FAI/FAIB	0.0	00					
QC Quality Control	Me	emo	0.	00			1B 10	413	

Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANGES						
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
								Tod Mg		
					-					
Part No:PAR #:		Fault Cate	gory: N	CR: Yes	No DQ	A:	Date:			
Resolution:			Disposition	n: Q						
NCR:			WORK ORDI	ER NON-CONFORMANO	E (NCF	1)				
DATE STEP	Description of NC	Corrective Action Section B	1 0: 0	cation	Approval Chief Eng	Approval				
DATE	SILF	Section A	Initial Chief Eng	Action Description Chief Eng			1 & Section C		QC Inspector	

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Work Order ID 61925

Thursday, September 09, 2010 12:54:33 PM



Page 2

Item ID:

D4180-3

Revision ID: PRELIM

Item Name:

Gusset

Start Date:

9/9/2010

Start Qty: 2.00

Required Date: 9/16/2010

Req'd Qty: 2.00



Accept



Setup Start

Stop



Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Cust Item ID:

Customer:

Run Start

OC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID

120

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

Set Up/ Run Hours Tool ID

Tool# Plan Accept Code Qty

Reject Qty

Reject Insp. Number Stamp

0.00 - 5 10/04/13

130

Brake NC

Brake NC

Bend as per dwg

0.00

0.00

Sp (3/09/14

Quality Control

QC5- Inspect part completeness to step on W/O

Memo

Memo

0.00 - inspectos to Pai

Sidonley (Ry)

Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANGE	ES				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:	
	R	esolution:	Disposition	1:	QA: N/C Closed: Date:				
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	R)			
DATE STEP	Description of NC		verificat			Approval	Approval		
DATE	SILF	Section A	Initial Chief Eng			Sign & Section		Chief Eng	QC Inspector
	V.								

H:\fFQRMS\Quality Assurance\approved QA\NCRWO RevE

Work Order ID 61925

Thursday, September 09, 2010 12:54:33 PM



Page 3

Item ID:

D4180-3

Revision ID:

PRELIM Gusset

Item Name: Start Date:

9/9/2010

QC:

Accept



Setup Start





Required Date: 9/16/2010

Start Qty: 2.00 Req'd Qty: 2.00

Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

Date: Date: Tooling:

0.00

SPC (Y/N):

Tool ID

Date:

Tool# Plan

Code

Date:

Run

Start

Reject

Stop

Sequence ID/ Work Center ID

150

HandFinish

Operation Description

Chemical Conversion Coat per QSI005 4.1

Set Up/ Run Hours

Accept Qty Qty

Reject

Number Stamp

Hand Finishing

QC3- Inspect Part Finish

0.00 BR 10 9-16

Quality Control

Memo

Memo

0.00

Identify as per dwg & Stock Location:

Ian

Packaging

Packaging

Memo

0.00

ZT 10-10-01 (

Dart Aer	ospace	Ltd
----------	--------	-----

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No	:	PAR #:	Fault Cat	tegory:	NCR: Yes	No DQ	A:	_ Date: _					
Resolution:			Dispositi	on:	QA: N/C CI	osed:		Date: _					
NCR:		V	VORK ORI	DER NON-CONFORMAL	NCE (NCR)							
D.175 075	CTED	Description of NC	Corrective Action Section B			Verification			Approval				
DATE	DATE STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Approval Chief Eng	QC Inspector					
									/				

Work Order ID 61925

Thursday, September 09, 2010 12:54:33 PM



Page 4

Item ID:

D4180-3

Revision ID: PRELIM

Item Name:

Gusset

QC:

Start Date:

9/9/2010 Required Date: 9/16/2010

Start Qty: 2.00

Req'd Qty: 2.00

Accept



Setup Start

Stop



Reference:

Approvals:

Process Plan:

Date:

Date:

Tooling: SPC (Y/N):

Date:

Cust Item ID:

Customer:

Date:

Run

Start

Stop



Sequence ID/

Work Center ID 180

Operation Description

QC21- Final Inspection - Work Order Release

Set Up/ Run Hours

0.00

Tool ID

Tool# Plan Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

Memo

0.00

Quality Control

POSITIVE RECALL

EFFECTIVE()

RELEASED

PS10,00

Dart Aerospace L	_td
------------------	-----

W/O:			W	ORK ORDER CHANGI	ES				
DATE	STEP	PRO	CEDURE CHA		Ву	Date	Qty	Approval Chief Eng /	Approval QC Inspector
								Prod Mgr	
Part No:PAR #:		PAR #:	Fault Cate	egory:	NCR: Yes	No DQA :		Date:	
Resolution:									
NCR:		V	VORK ORD	ER NON-CONFORMA	NCE (NCR)			
DATE OFFI	CTED	Description of NC			on B	Verifica	ation	Approval	Approval
DATE	ATE STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector	
							_		
						_			1

Picklist Print

Thursday, September 09, 2010 12:54:38 PM

Work Order ID: 61925

Parent Item: D4180-3

Comments:

Parent Item Name: Gusset



Start Date: 9/9/2010

Required Date: 9/16/2010

Start Qty: 2.00 Required Qty: 2.00

IPP Rev:A 10.09.09 new issue DD verf:EC


Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Otv	Qty Issued	Date Issued	Status
M6061T6S.125		Purchased	No			100	sf	125.2600	0.114	0.24			
6061-T6 ,125 Sheet		II.									12 117-6	+3	

Location	Loc Qty	Loc Code		
MAT21	125.26			411
113608	96			(4)
114352	29.26		114357	

Page 1

Dart Aerosp	pace Ltd
-------------	----------

W/O:			V	ORK ORDER CHANGE	S				
DATE	STEP	PRO	CEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								ı	
Part No: PAR #:			Fault Ca	tegory:	NCR: Yes No DQA: Date:				
	Resolution:			ion:	QA: N/C C	losed:		Date:	
NCR:		1	WORK OR	DER NON-CONFORMA	NCE (NCF	₹)			
DATE STEP		Description of NC		Corrective Action Section		Verification			Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Date Section C		on C	Chief Eng	QC Inspector
					1				



Dart Aerosp	ace Ltd	
-------------	---------	--

W/O:			W	ORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:N	CR: Yes	No DQA	٨:	Date:	
			Disposition:						
NCR:			WORK ORD	ER NON-CONFORMANO	E (NCR)			
DATE	CTED	Description of NC	Corrective Action Se		Verificati		ation	n Approval	Approval
DATE	STEP Description of NC Section A		Initial Chief Eng	Action Description Chief Eng	cription Sign & Secti				QC Inspector

Work Order:	6193
Part Number:	04180-3
	Page 1 of 1
	Part Number:

	1					
Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Com	ments
+ 005 - 061	,130	>		V BOX		
4.7		9	*	V		
47		7		V		
4				V		
47		80-		V		
LsI	***************************************	7		V		
d				V		
1				V		
-		1		V		
41				V		
+/				V		
L-/				A		
				V		
1.01		1		V		
				IV		
12 1010	1175	7				
	+					
			+			
	1		-			
	-	-				2%
		-	-			
	-	-			-	
			-	lot	1	
	Audited by:	IS		Prototype A	pproval:	N/A
1		1			Date:	N/A
10-9-13	inspectio	ID DAT	Don unto		- veil by a different	Approve
Change New Issue	113141		\	K	J/JLM	Applove
	Tolerance 1.005 - 0.1 1.005 - 0.1 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000 1.000	Tolerance	Tolerance	Tolerance	Tolerance	Tolerance

New Issue

Dart	Aerospa	ace Ltd
Duit	ACIUSDI	ICC LIU

	- opas									
W/O:			WC	RK ORDER CHANGE	S					
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No.		PAR #	Fault Cate	TOTY:	NCB: Vas	No DO	۸٠	Date		
Part No: PAR #:			Disposition:							
NCR:				ER NON-CONFORMA						
		5	Corrective Action Sect		n B	V-JE-N				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		Verification Section C	Approval Chief Eng	Approval QC Inspector	

